



# United States Steel Corporation

## BOP Flux Handling Baghouse Dust

Signal Word: **DANGER**

Symbols:



### HAZARD STATEMENTS:

May cause cancer.

May cause mechanical irritation to skin and damage to lungs.

Causes damage to lungs, autoimmune system and kidneys through prolonged or repeated exposure.

Causes severe skin burns and serious eye damage.

### PRECAUTIONARY STATEMENTS

Do not breathe dusts.

Wear protective gloves / protective clothing / eye protection / face protection.

Wash thoroughly after handling.

Obtain special instructions before use.

Do not handle until all safety precautions have been read and understood.

Do not eat, drink or smoke when using this product.

If exposed, concerned or feel unwell: Get medical advice/attention, call a poison center or doctor/physician.

If inhaled: Remove person to fresh air and keep comfortable for breathing. Immediately call a poison center or doctor/physician.

If in eyes: Rinse cautiously with water for several minutes. Remove contact lenses, if present and easy to do.

Continue rinsing. Immediately call a poison center or doctor/physician.

If on skin (or hair): Take off immediately all contaminated clothing. Rinse skin with water/shower. Wash contaminated clothing before reuse.

If swallowed: Rinse mouth. Do NOT induce vomiting.

Store locked up.

Dispose of contents in accordance with federal, state and local regulations.